

SSM 49580 - 2020-2021 Explorer/Aviator/Police Interceptor Utility - Various Electrical Concerns - 3 And 4 Post Fuse Array On BJB Released For Service

Some 2020-2021 Explorer/Aviator/Police Interceptor Utility vehicles may exhibit various electrical concerns due to an open 3 or 4 post fuse array on the high current battery junction box (BJB). Service part LU5Z-14526-ALD has been released for the 3 post fuse array and LU5Z-14526-ANC has been released for the 4 post fuse array. It is no longer necessary to order the complete wiring harness to obtain these parts.

APPLICABLE VEHICLES

2020 CAR: TV U611N AVIATOR
2020 CAR: TW U625N EXPLORER
2021 CAR: TV U611N AVIATOR
2021 CAR: TW U625N EXPLORER