

## **SSM 49691: 2021 Mustang Mach-E - Missing Keyless Entry Secure Code Card**

Some 2021 Mustang Mach-E vehicles may be missing the keyless entry secure code card. To retrieve the keyless entry code from the body control module (BCM), connect the Ford Diagnostic and repair tool > confirm the VIN > goto toolbox > select BCM Factory Keyless Entry Code > press Download to retrieve and display the factory keyless entry code > then press Run to get the code.

Vehicles:

2021 Mustang Mach-E (CX727N) (GW)