

SSM 49739: 2021 Edge/Nautilus - VIN Mismatch Message In Both Side Obstacle Detection Control Modules When Using FDRS

Some 2021 Edge/Nautilus vehicles may exhibit a VIN mismatch condition in both side obstacle detection control modules (SODL/SODR) during Ford Diagnosis and Repair System (FDRS) vehicle identification. This may be due to an incorrect As-Built configuration. Do not attempt to replace the SODL and/or SODR modules. This condition does not affect vehicle function. Engineering is currently working on a solution. Monitor OASIS for updates.

Vehicles:

2021 Edge (CD539N) (DQ)

2021 MKX/Nautilus (U540N) (D9)