SSM 49810 - 2021 Mustang Mach-E - Buzz Noise From The Instrument Panel Cluster (IPC)

Some 2021 Mustang Mach-E vehicles may exhibit a buzzing noise from the IPC thatchanges with the brightness setting. This is a normal operating characteristic of the vehicle and replacement of the IPC and/or other parts is not recommended. If compared to like vehicles some variation may be noted and should be considered normal.

APPLICABLE VEHICLES 2021 CAR: GW CX727N C-EV