

SSM 49837 - 2021 Mustang Mach 1 - Equipped With Handling Package - Missing Front Splitter During PDI - Built On Or Before 25-Mar-2021

Some 2021 Mustang Mach 1 vehicles equipped with the handling package and built on or before 25-Mar-2021 may have been shipped to dealers without a front splitter. The front splitter is a loose shipped item that should be installed during the pre-delivery inspection (PDI) process. For more information, access the following dealership communication located on FMCDealer.com by copying and pasting the following link into a web browser <https://www.fmcdealer.dealerconnection.com/content/fmcdealer/en/us/edc/2021/qafmm1p5321.html>. The communication can also be found by navigating to the dealer communications page on FMCDealer.com. On the 'Dealer Communication' page, select 'May 2021' in the Month/Year category. Scroll down to 'May 3, 2021' and click on the link 'Q&A: 2021 Ford Mustang Mach 1 Part'.

APPLICABLE VEHICLES
2021 CAR: ZG S550N MUSTANG