

SSM 50065 - 2021 Bronco – 5 Door Hard Top Models – Poor Sirius XM Satellite Radio Reception And/Or Signal Loss In Rural Areas

Some 2021 Bronco 5 door models equipped with a hard top roof configuration may exhibit poor Sirius XM satellite radio reception and or signal loss in rural areas with dense foliage, tall buildings, or other similar obstructions. No additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle and engineering is currently working on a solution for this condition that is expected to be available for service in January 2022. In addition, if the vehicle is equipped with the optional factory roof rails and crossbars this may further degrade the reception. Removing the roof rails and crossbars may improve reception performance. Monitor OASIS for additional information and schedule a service appointment with the customer once the repair becomes available.

APPLICABLE VEHICLES
2021 TRUCK: G1 U725N BRONCO