

SSM 50162 - 2021 Mustang Mach-E and F-150 - 360 Degree Camera System - Reverse Brake Assist Unavailable Message And DTC B1578:78 In The IPMA After An On-Demand Self Test

Some 2021 Mustang Mach-E and F-150 vehicles equipped with a 360 degree camera system may experience a Reverse Brake Assist Unavailable message displayed in the instrument panel cluster (IPC) and diagnostic trouble code (DTC) B1578:78 in the image processing module A (IPMA) after an on-demand self test is performed. To clear the Reverse Brake Assist Unavailable message displayed in the IPC, download and run the 360 Degree View Camera Alignment app for the IPMA using the latest version of the Ford Diagnosis and Repair System (FDRS). Once the 360 Degree View Camera Alignment routine is successful and the Reverse Brake Assist Unavailable message is no longer displayed in the IPC, perform a continuous memory self test. If any DTC's persist, continue with Workshop Manual (WSM), Section 419-07 diagnostic procedures.

APPLICABLE VEHICLES
2021 TRUCK: FD P702N F150
2021 CAR: GW CX727N C-EV