

**SSM 50380 - 2020-2022 F-Super Duty - 6.7L - 175 inch Wheelbase -  
Thump/Whine/Knock Noise From The Fuel Tank After Performing TSB 21-  
2057 - Built On Or Before 23-Sep-2021**

Some 2020-2022 F-Super Duty pickup vehicles equipped with a 6.7L engine, 175 inch wheelbase, and built on or before 23-Sep-2021 may exhibit a thump/whine/knock noise from the midship fuel tank at idle or during key on, engine off (KOEO) after performing TSB 21-2057. The noise may be more pronounced at fuel levels at or below 1/4 tank. This may be due to the fuel pump. To correct the condition, replace the fuel pump and sender assembly with service part HC3Z-9H307-AP. For claiming, use causal part 9H307 and applicable labor operations in Section 08 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES

2020 - 2021 TRUCK: FE P558N SUPER DUTY

2022 TRUCK: FE P558N SUPER DUTY