

## **SSM 50963**

### **2021-2022 F-150 Raptor - Rattle Noise From The Exhaust - Built On Or Before 06-Jun-2022**

Some 2021-2022 F-150 Raptor vehicles built on or before 06-Jun-2022 may experience a rattle noise from the exhaust near the exhaust tailpipe actuators. This condition does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to drive the vehicle, and engineering is currently working on a solution for this condition that is expected in September 2022. Replacement of the muffler will not resolve this condition. Monitor OASIS for additional information and schedule service appointments for customers once the repair becomes available.