

---

## **SSM 51142 2022 Maverick - 2.5L FHEV - Brakes Grab During Light Braking When Applied At Or Below 6.2 Mph (10 Km/h)**

---

Some 2022 Maverick vehicles equipped with a 2.5L full hybrid electric vehicle (FHEV) powertrain may exhibit a condition where the brakes may grab during light braking at or below 6.2 mph (10 km/h). This may be due to the software in the anti-lock brake system module (ABS). This condition does not affect vehicle safety/performance and no additional diagnosis or service is required for this condition at this time. Inform customers that they can continue to safely drive the vehicle, and engineering is currently developing a software update that is expected in the last week of November 2022. Once the software update is available, contact the customer and schedule a follow-up appointment for repair in December 2022. Monitor OASIS for updates.