

SSM 51234

2014-2021 F53 Motorhome/F-59 Commercial Stripped Chassis - Pinion Seal Leak

Some 2014-2021 F53 Motorhome/F-59 Commercial Stripped Chassis may exhibit a pinion seal leak. A new part number is available to resolve this concern, MU9Z-4676-A. For claiming, use causal part number 4676 and applicable labor times in Section 04 of the Service Labor Time Standards (SLTS) Manual.