

SSM 51293

2022-2023 Lincoln Aviator - Multi-Contour Front Seat Modules Serviced Separately From Seat Back Frame

2022-2023 Lincoln Aviator vehicles equipped with multi-contour front seats have driver seat control module G (SCMG) and passenger seat control module H (SCMH) seat modules available separately at a lower level service part from the seat back frame (5461018/7861018/7861019). If diagnosis determines that replacement of either multi-contour front seat module is required, it is not necessary to replace the complete seat back frame. Refer to the service part catalog for the correct front seat module part number (14F548/14F549) and Workshop Manual (WSM) Section 501-10A for replacement procedures.