

## SSM 51622

2022-2023 Aviator (U611N) (TV)

2022 Corsair (CX483N) (TF)

2022 Escape (CX482N) (TC)

2022-2023 Expedition (U553) (B8)

2022-2023 Explorer (U625N) (TW)

2022-2023 Navigator (U554) (B9)

### Multiple Vehicle Lines - No Longer Equipped With A Hands Free Liftgate System

2022-2023 Explorer/Aviator vehicles built on or after 28-May-2022, 2022-2023 Expedition/Navigator vehicles built on or after 08-Jun-2022 and 2022 Escape/Corsair vehicles built on or after 01-Jun-2022 are no longer equipped with a hands free liftgate system. The vehicle is not misbuilt. The addition of any parts is not a warrantable repair. Do not submit a claim for this condition.