

SSM 46232	Some 2016-2017 Focus RS with SYNC 3 may exhibit a condition in which a Sound Mode selection is displayed in the front display interface module (FDIM) Sound Settings screen. Focus RS audio systems are not equipped with Sound Mode Surround Sound. To correct this condition, perform the SYNC accessory protocol interface module (APIM) standard programming procedure, refer to Workshop Manual (WSM), Section 415-00. For claiming, use causal part 14G371 and applicable labor operations in section 10 of the service labor time standards (SLTS) manual.
--------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------