

SERVICE ALERT

Date: 2016-08-16

Service Alert
No: SA-001306

Subject: 2017 MAZDA3 AND MAZDA6 - DO NOT UPDATE THE MAZDA
CONNECT SYSTEM WITH AN EARLIER VERSION OF SOFTWARE

The 2017 Mazda3 and Mazda6 have the latest MAZDA CONNECT software (Version 59). DO NOT attempt to update with the software version available on MS3 (Version 55). If you update to an earlier version of software, the CMU will need to be sent in and reprogrammed. Contact Technical Hotline if this happens for shipping information.