

Clicking, Ticking, or Rattling from Front when Driving over Bumps

AFFECTED VEHICLES

2007–11 CR-V and 2007–10 Odyssey

When driving over bumps, are you hearing a clicking, ticking, or rattling from the front of the vehicle? Dry front brake caliper pins could be the culprit.

To check for this, lightly apply the brakes while driving over some bumps. If the noise goes away, the caliper pins need more grease. Repack them with Honda Caliper Slide Pin Grease (P/N 08C30-B0224M).

If the noise comes back after repacking the caliper pins, you'll need to replace the upper caliper pins (upper caliper pin B, the ones with the rubber on the end) with the ones from the Brake Caliper Pin Set (P/N 06452-SHJ-305). This set includes two upper caliper pins and a grease packet.