



**NUMBER:** 08-026-15 REV. A

**GROUP:** Electrical

**DATE:** April 03, 2015

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-026-15, DATED MARCH 21, 2015, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **\*\*ASTERISKS\*\*** AND INCLUDES UPDATING TO AN RRT STATUS.**

**\*\*THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-031. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.\*\***

***SUBJECT:***

Incorrect Language Displayed On The Cluster And Radio

***OVERVIEW:***

This bulletin involves changing the vehicle language settings to English.

***MODELS:***

2015 (BU) Jeep Renegade

**NOTE: This bulletin applies to vehicles built on or before March 03, 2015 (MDH 0303XX) equipped with one of the following radios:**

- Uconnect 3.0 AM/FM (sales code RA1).
- Uconnect 5.0 AM/FM/BT (sales code RA2).
- Uconnect 8.4AN AM/FM/BT/ACCESS/NAV (sales code RA4).

***SYMPTOM/CONDITION:***

The customer and/or dealer may want to change the language displayed in the radio and cluster to English.

***DIAGNOSIS:***

**\*\*If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.\*\***

**REPAIR PROCEDURE:**

1. Using the vehicle sales codes which radio does the vehicle have, RA1, RA2 Or RA4?
  - a. RA1 radio, Proceed to [Step #2](#)
  - b. RA2 radio, Proceed to [Step #8](#)
  - c. RA4 radio, Proceed to [Step #15](#)

**RA1 Radio Language Setup Procedure**

**NOTE: The word on the cluster display may be hard to understand, since they may be in a foreign language. Chose the selection that will be in the same location on the cluster's displayed as shown in the images below.**

2. Using the buttons on the steering wheel, scroll to menu 8 in the Electronic Vehicle Information Center (EVIC).



**Fig. 1 Select Menu 8**

1 - Correct Selection

---

3.



**Fig. 2 Select Display**

1 - Correct Selection

---

4.



**Fig. 3 Select Language**

1 - Correct Selection

---

5. First select French or Spanish, before selecting English.



**Fig. 4 Select Either French or Spanish**

1 - Either Selection Will Be Correct

---

6.



**Fig. 5 Select English**

1 - Correct Selection

---

7. This Bulletin has been completed.

## RA2 Radio Language Setup Procedure

**NOTE: The word on the radio display may be hard to understand, since they may be in a foreign language. Chose the selection that will be in the same location on the radio's displayed as shown in the images below.**

8. Press the hard key in the lower right corner of the radio display screen labeled, More.



**Fig. 6 Press Hard Key More**

1 - Correct Selection

---

9.



**Fig. 7 Select Settings**

1 - Correct Selection

---

10.



**Fig. 8 Select Display**

1 - Correct Selection

---

11.



**Fig. 9 Select Language**

1 - Correct Selection

---

12. First select French or Spanish, before selecting English.



**Fig. 10 Select Either French or Spanish**

1 - Either Selection Will Be Correct

---



13.



**Fig. 11 Select English**

1 - Correct Selection

---

14. This Bulletin has been completed.



## RA4 Radio Language Setup Procedure

**NOTE:** The word on the radio display may be hard to understand, since they may be in a foreign language. Chose the selection that will be in the same location on the radio's displayed as shown in the images below.

15. Press the upper hard key on the right side of the radio display screen.



***Fig. 12 Press Hard Key Settings***

1 - Press Hard Key

---

16.



**Fig. 13 Select Display**

1 - Correct Selection

---

17.



**Fig. 14 Select Display Mode**

1 - Correct Selection

---

18.



**Fig. 15 Select Set Language**

1 - Correct Selection

---

19. First select French or Spanish, before selecting English.



**Fig. 16 Select Either French or Spanish**

1 - Either Selection Will Be Correct

---

20.



**Fig. 17 Select English**

1 - Correct Selection

21. This bulletin has been completed.

**POLICY:**

Reimbursable within the provisions of the warranty.

**/TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-45-07-94	Change Language Settings To English (0 - Introduction)	6 - Electrical and Body Systems	0.2Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------