

**FUEL FILLER NOZZLE SHUTTING OFF BEFORE  
ADDING 3.8L (1 GALLON)—BUILT ON OR BEFORE  
4/8/2013**

**TSB 13-6-1**

**FORD:**  
2013 Fusion

**LINCOLN:**  
2013 MKZ

**ISSUE**

Some 2013 Fusion and MKZ vehicles built on or before 4/8/2013 may exhibit a customer concern of the fuel filler nozzle shutting off before adding 3.8L (1 gallon).

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

Variations in fuel filler nozzles, flow rates and pressure may result in premature shutting off of the fuel filler nozzle, making it difficult to fill the fuel tank.

1. Does the customer state the fuel filler nozzle consistently shuts off before adding 3.8L (1 gallon) of fuel?
  - a. Yes - install a new fuel tank filler pipe. Refer to Workshop Manual (WSM), Section 310-01.
  - b. No - this article does not apply. Refer to WSM, Section 310-01 for normal diagnosis.

**WARRANTY STATUS:** Eligible Under Provisions Of New Vehicle Limited Warranty Coverage And Emissions Warranty Coverage  
Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
130601A	2013 Fusion/MKZ: Replace The Fuel Filler Pipe (Do Not Use With Any Other Labor Operations)	0.7 Hr.

**DEALER CODING**

<b>BASIC PART NO.</b>	<b>CONDITION CODE</b>
9034	42

<b>PART NUMBER</b>	<b>PART NAME</b>
DG9Z-9034-K	Filler Pipe - FWD
DG9Z-9034-L	Filler Pipe - PHEV
DG9Z-9034-M	Filler Pipe - AWD

**NOTE:** The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supercede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.