



To All Lamborghini Dealers and Licensed Service Point
From Customer Service Department
Subject Water drain in alternator pipe
Group 140.9.03
Date 30.01.2007
Pages 5

Automobili
Lamborghini S.p.A.

Subject

Water drain in alternator pipe

Model / VIN-Range

Gallardo (Coupe and Spyder) from VIN G52500 to VIN G74934.

Information to the field

In case you have a vehicle in the workshop Lamborghini recommends creating a hole in the front alternator pipe.

This modification must be performed on all cars involved at the next service.

Lamborghini recommends you to carry out this upgrade aiming to extend the life of these components.

Field solution

To create a hole to drain the water from the alternator pipe.

Spare Parts

No spare parts needed.



Warranty Claim data

The warranty reimbursement request for this rework action will be managed by the following standard Warranty Claim procedure.

Campaign Code:	L140-A.01.07 (Coupè) / L715-A.01.07 (Spyder)
Campaign Description:	Water drain alternator pipe
Cost Code:	50
Component Code:	CCA0107
Trouble Code:	220
Labour Code:	CCA0107100
Labour Time:	0.2 h

Your Area Manager is at full disposal for further information.

Best regards

Product Service

Necessary material

- Screw driver
- Soldering station



Description of operations

- 1.1 Adopt all precautions to prevent car damages and to work safe.
- 1.2 Raise the car on the lift.
- 1.3 Using a screw driver; create a small hole near the black clamp on the alternator pipe. (See picture 2). Please **BEWARE** when piercing a hole in the pipe because water may be released.


Pic.2



1.4 NOTE : Next operation requires your full attention.

1.5 PLEASE BE CAREFUL when plugging the soldering station into electric outlet.

1.6 Beware that the pipe is void of all water before the melting process.

1.7  Now with the soldering station powered, melt a 5mm hole in the pipe.
(Picture 3)

Pic. 3

