



To All Lamborghini Dealers and Licensed Service Point
From Customer Service Department
Subject New bushings and supports for the front torsion bar
Group 147.4.01.00
Date 17.11.2005
Pages 3

Automobili
Lamborghini S.p.A.

Subject

New bushings and supports for the front torsion bar.

Model / VIN-Range

Murciélago coupe MY 02-03-04.

Information to the field

In case you have to replace front torsion bar bushings or supports on Murciélago MY 02-03-04, please be informed that the p/n 400511324 – bushing for Murciélago torsion bar – and 400411031A – support for Murciélago torsion bar – have been replaced by new rubber bushings (p/n 400511324C) and new supports (p/n 400411031D) on the spare parts catalogue.

The new bushings and supports are compatible with torsion bar p/n 0051003973 fitted on MY 02-03-04.

Important remark: In case of first replacement of old parts with the new ones, due to the different technical specifications of the new bushings and supports, it's mandatory to replace the complete kit (2 bushes + 2 supports) on the involved bar, even if only one of the old part is defective, because the new parts are not compatible with the old ones.



Spare Parts

For the replacement of old bushings and supports with new bushing/supports kit on a torsion bar:

2 rubber bushings - p/n 400511324C - available at Lamborghini warehouse

2 supports - p/n 400411031D - available at Lamborghini warehouse

Warranty Claim data

Important: use these data only in case the replacement is done in warranty and only for the first replacement (old style to new style bushings/supports), not for following (new to new) replacements.

Available on Lamborghini Web Portal in the Warranty section “Available campaigns”.

Bulletin code:	L147-T.03.05
Bulletin description:	Front torsion bar bushings/supports replacement
Cost Code:	55
Component Code:	T0305
Trouble Code:	220
Labour code:	T0305100
Labour Time:	1 h

Your Area Manager is at your full disposal for further information.

Best regards


Product Service



Old parts:



Old bushing for torsion bar p/n 400511324



Old support for torsion bar p/n 400411031A

New parts:



New bushing for torsion bar p/n 400511324C



New support for torsion bar p/n 400411031D

Description of operations

For a detailed description of torsion bar assembling/disassembling operations see 147.04.01 group on the web technical documentation.