



To All Lamborghini Dealers and Licensed Service Point
From Customer Service Department
Subject Grease for door shock absorber ball joint
Group 147.8.37
Attachments -
Date 11.10.05
Pages 4

Automobili
Lamborghini
S.p.A.

Subject

Grease for door shock absorber ball joint

Model / VIN-Range

All Murcièlago and Diablo models

Information to the field

In the case of noise coming from the door shock absorbers ball joints, you must lubricate the ball joints using grease with the following technical specifications:

- antioxidant lithium grease, working temperature range -40°C to +125°C

See attached instructions to disconnect the ball joint in order to apply the grease.

Your Area Manager is at your full disposal for further information.

Best regards

Customer Service

Via Modena,12
I-40019 Sant'Agata
Bolognese
Tel +39 051 6817 652
Fax +39 051-6817 709



Description of operations

- 1.1 Adopt all precautions to prevent car damages and to work safe.
- 1.2 Open completely the door and use a support to keep it opened once the ball joint is disconnected.
- 1.3 Remove the ball joint safety pin (rotate and unthread to remove it, see pic.1-2)



Picture 1



Picture 2

1.4 Disconnect the ball joint and clean it with a cleaning solution (pic.3).



Picture 3



1.5 Apply the grease on the ball joint (pic.4).



Picture 4

1.6 Now you can reconnect the ball joint, reassemble the safety pin and remove the excess grease.