



VOLUME


2

GROUP
ChassisMODEL
SephiaNUMBER
005DATE
August 1999

Technical Service Bulletin

SUBJECT:**Sephia Brake Pads**

This bulletin provides information on a change in the Sephia brake pad. A new friction material has been developed to improve brake pad wear and reduce the possibility of brake vibration and noise.



All 2000MY Sephia models are equipped with these improved brake pads. In addition, these new brake pads supercede all previous replacement brake pads for all Sephia models 1994 to present.

*** NOTICE**

- It is recommended that the brake rotors be machined or replaced when new brake pads are installed.
- Replacement of brake pads due to normal wear is the responsibility of the customer and not a warrantable repair.
- Always use a torque wrench when reinstalling wheel lug nuts.

File Under: Chassis**Circulate To:**☒ Service Advisor(s) ☒ General Manager ☒ Technician(s) ☒ Service Manager ☒ Body Shop Manager ☒ Parts Manager

SUBJECT:

Sephia Brake Pads

Part Number Information

Description	Previous P/N	New P/N
Brake Pad Set - Front	0K2A3 33 23ZB	0K2A4 33 23Z