

NUMBER:	23-046-15
GROUP:	Body
DATE:	December 02, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

# SUBJECT:

Liftgate Fiat Emblem Loose

# **OVERVIEW:**

This bulletin involves replacing the liftgate Fiat emblem.

## MODELS:

2016 (FB) Fiat 500x

- NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA
- NOTE: This bulletin applies to vehicles built on or before April 05, 2015 (MDH 0405XX).

### SYMPTOM/CONDITION:

The customer may describe the liftgate Fiat emblem is loose.

### DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

### PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	6AU23LRSAA	Emblem, Fiat
2	68073915AA	Fastener, Emblem
1	NPN	3M™ 08061 Emblem Adhesive
AR	NPN	Isopropyl Alcohol

### NOTE: Isopropyl alcohol is considered shop supply (not on claim).

# SPECIAL TOOLS/EQUIPMENT REQUIRED:

C-4755 Trim Stick
-------------------

# **REPAIR PROCEDURE:**

- 1. Mask around the Fiat emblem to prevent damage to the liftgate paint surface (Fig. 1).
- 2. Using a non-metallic trim stick or equivalent (2), remove the Fiat emblem (1) (Fig. 1).



Fig. 1 Apply Tape To Protect Surface And Remove Loose Fiat Emblem

- 1 Fiat Emblem
- 2 Trim Stick
- 3. Remove any residual adhesive foam tape pieces from the liftgate surface (Fig. 2).



Fig. 2 Remove Residual Adhesive Foam Tape From Liftgate

4. Using a non-metallic trim stick or equivalent (2), remove and discard the emblem fasteners (1) (Fig. 3).




Fig. 3 Remove And Discard Emblem Fasteners

- 1 Emblem Fasteners
- 2 Trim Stick
- 5. Clean the liftgate emblem application surface using isopropyl alcohol (Fig. 4).



Fig. 4 Clean Emblem Application Surface Area

6. Install the new emblem fasteners into the liftgate emblem holes (Fig. 5).




Fig. 5 Install New Emblem Fasteners Into Liftgate Holes

- NOTE: Only if the original emblem was lost, perform Step #7. Otherwise reuse the existing emblem and proceed to Step #8.
- 7. Remove the adhesive tape liner from the back of the new Fiat emblem (Fig. 6).



Fig. 6 Remove Adhesive Tape Liner From New Emblem

8. Apply beads of 3M<sup>™</sup> emblem adhesive to the mounting tape surface of the Fiat emblem. Apply only an appropriate amount of adhesive in order to prevent adhesive squeeze out beyond the emblem outer edge (Fig. 7).



# Fig. 7 Apply Adhesive To Emblem Adhesive Tape Surface

- 9. Align the Fiat emblem to the emblem fasteners and install the emblem to the liftgate.
- 10. Apply finger pressure to the emblem for at least 10 seconds to ensure proper adhesion of the emblem to the liftgate (Fig. 8).



Fig. 8 Install Fiat Emblem To Liftgate

11. Remove the protective masking material from the liftgate (Fig. 9).



Fig. 9 Remove Protective Masking Material From Liftgate

## POLICY:

Reimbursable within the provisions of the warranty.

## TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-03-08-9A	Liftgate Emblem, Fiat - Replace (0 - Low Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

### FAILURE CODE:

ΖZ

Service Action

### PART REIMBURSEMENT DETAIL:

Part No:	Description	
NPN	3M™ 08061 Emblem Adhesive	

NOTE: This part number is for reimbursement only and will need to be claimed for the value of Part No. 08061 or it will be rejected. If this is a non-MOPAR part or product, a copy of the invoice showing the purchase of the non-MOPAR part or product needs to be attached to the reimbursement claim.