



**To:** All Lamborghini Dealers and Service Points  
Workshop and Service Manager

**From:** After Sales

**Pag.:** 10

**Subject:** Gallardo Service Campaign

**Date:** 14.07.2004

Automobili  
Lamborghini S.p.A.

Dear Lamborghini Dealer,

Service Campaigns are meant to maintain a high quality level of the product.  
Therefore, we have enclosed the necessary instructions in order to carry out the above mentioned Service Campaign.

**Description:**

We have gathered the several actions in order to limit the necessary time for the repair of the involved vehicles.

**Information for the Customer**

Automobili Lamborghini will send at the same time a letter inviting the customer to make an appointment with the authorized Lamborghini Service Point in order to have his/her vehicle updated (see the attached one copy).

Before starting to call the customer make sure you have all needed parts and tools in your workshop.

**Vehicles involved:**

Please see the list below.



## Group 1

From VIN		To VIN
ZHWGE11__4LA00060		ZHWGE11__4LA00086
Required time	10,70	
Procedure	Description	
L140-01.04	Water pump replacement	
L140-02.04	Rear spoiler anchorage	
L140-03.04	BJA control unit replacement	
L140-04.04	Replacement gearbox nuts	
L140-05.04	Correct connector fitting (driver and passenger sides)	
L140-06.04	Engine compartment and grill bolt replacement	
L140-07.04	Replacement of thermo coupling interface and correct assembling	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

## Spare Part kit for one vehicle of Group 1:

p/n 0R1400007 and p/n 0R1400013 with the following parts

Operation	Required Spare parts	P/ n	Quantity
L140-01.04	Water pump	07L121011D	1
L140-02.04	Rear spoiler: Component to be glued	-	-
L140-03.04	BJA ecu: Check version, replace with new one	401941567	1
L140-04.04	Screws	N 10664501	5
L140-05.04	Clip	N 90926601	10
L140-06.04	Screw kit	OR1400002	1
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-



## Group 2

From VIN		To VIN
ZHWGE11_4LA00087		ZHWGE11_4LA00089
<b>Required time</b>	8,20	
<b>Action</b>	<b>Description</b>	
L 140-02.04	Rear spoiler anchorage	
L140-03.04	BJA control unit replacement	
L140-04.04	Replacement gearbox nuts	
L140-05.04	Correct connector fitting (driver and passenger sides)	
L140-06.04	Engine compartment and grill bolt replacement	
L140-07.04	Replacement of thermo coupling interface and correct assembling	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

### Spare Part kit for one vehicle of Group 2:

p/n 0R1400008 and p/n 0R1400013 with the following parts

Operation	Required Spare parts	P/ n	Quantity
L140-02.04	Rear spoiler: Component to be glued	-	-
L140-03.04	BJA ecu: Check version, replace with new one	401941567	1
L140-04.04	Screws	N 10664501	5
L140-05.04	Clip	N 90926601	10
L140-06.04	Screw kit	OR1400002	1
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts		
L140-09.04	Kit Coil cover		1
L140-10.04	No parts		



### Group 3

From VIN		To VIN
ZHWGE11__4LA00090		ZHWGE11__4LA00760
Required time	7,85	
Action	Description	
L140-04.04	Replacement gearbox nuts	
L140-05.04	Correct connector fitting (driver and passenger sides)	
L140-06.04	Engine compartment and grill bolt replacement	
L140-07.04	Replacement of thermo coupling interface and correct assembling	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

### Spare Part kit for a vehicle of Group 3:

p/n 0R1400009 and p/n 0R1400013 with the following parts

Operation	Required Spare parts	P/ n	Quantity
L140-04.04	Screws	N 10664501	5
L140-05.04	Clip	N 90926601	10
L140-06.04	Screw kit	OR1400002	1
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-



#### Group 4

<b>From VIN</b>		<b>A VIN</b>
ZHWGE11_4LA00761		ZHWGE11_4LA00773
<b>Required time</b>	4,75	
<b>Action</b>	<b>Description</b>	
L140-05.04	Correct connector fitting (driver and passenger sides)	
L140-06.04	Engine compartment and grill bolt replacement	
L140-07.04	Replacement of thermo coupling interface and correct assembling	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

#### Spare Part kit for one vehicle of Group 4:

p/n 0R1400010 and p/n 0R1400013 with the following parts

Operation	Required Spare parts	P/ n	Quantity
L140-05.04	Clip	N 90926601	10
L140-06.04	Screw kit	OR1400002	1
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-



## Group 5

<b>From VIN</b>	<b>A VIN</b>
ZHWGE11_ _4LA00774	ZHWGE11_ _4LA00934
<b>Required time</b>	3,25
<b>Action</b>	<b>Description</b>
L140-06.04	Engine compartment and grill bolt replacement
L140-07.04	Replacement of thermo coupling interface and correct assembling
L140-08.04	ECUs reflash
L140-09.04	Coil cover assembly
L140-10.04	Checklist: underbody

**Spare Part kit for one vehicle of Group 5:**

**p/n 0R1400011 and p/n 0R1400013 with the following parts**

<b>Operation</b>	<b>Required Spare parts</b>	<b>P/ n</b>	<b>Quantity</b>
L140-06.04	Screw kit	OR1400002	1
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-



## Group 6

<b>From VIN</b>		<b>A VIN</b>
ZHWGE11_ _4LA00935		ZHWGE11_ _4LA01029
<b>Required time</b>	2,75	
<b>Action</b>	<b>Description</b>	
L140-07.04	Replacement of thermo coupling interface and correct assembling	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

## Spare Part kit for one vehicle of Group 6:

p/n 0R1400012 and p/n 0R1400013 with the following parts

Operation	Required Spare parts	P/ n	Quantity
L140-07.04	Protective cover	400919221A	1
	Thermo coupling interface	400919935A	1
	Clip	N 90926601	1
	Clamp	N 10562301	1
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-



## Group 7

<b>From VIN</b>		<b>A VIN</b>
ZHWGE11_ _4LA001030		ZHWGE11_ _4LA01477
<b>Required time</b>	2,00	
<b>Action</b>	<b>Description</b>	
L140-08.04	ECUs reflash	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

**Spare Part kit for one vehicle of Group 7:**

**p/n 0R1400013 with the following parts**

<b>Operation</b>	<b>Required Spare parts</b>	<b>P/ n</b>	<b>Quantity</b>
L140-08.04	No parts	-	-
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-





### Group 8

<b>From VIN</b>		<b>A VIN</b>
ZHWGE11_ _4LA01478		ZHWGE11_ _4LA01650
<b>Required time</b>	1,00	
<b>Action</b>	<b>Description</b>	
L140-09.04	Coil cover assembly	
L140-10.04	Checklist: underbody	

### Spare Part kit for one vehicle of Group 8: p/n 0R1400013

Operation	Required Spare parts	P/ n	Quantity
L140-09.04	Kit Coil cover	-	1
L140-10.04	No parts	-	-

**Technical information:**

The repair is addressed to the Gallardo vehicles , whose chassis number is included in the here above lists.

For all included vehicles the attached “Fax Form21” must be filled in and sent by fax **on the same** day the repair is completed. The actions without documentation will NOT be reimbursed.

**Reimbursement**

Fill in all information in the Warranty Web System attaching the copy of the “Fax Form21” and the file of ECU up date confirmation, as described in the procedure L140-08-04.

**Solution:**

All repairs are described in the attached procedures.

**Network information:**

All Lamborghini Dealers and Service Points will be informed about this operation.

**Parts for vehicle:**

Every group has its own spare part kits and the first needed kits will be send by the Spar Parts Department. If you need more please advice us.

**Replaced material:**

The replaced material must be labelled and conserved in one box for each car in your workshop for at least 6 months.

Your Area Manager is at full disposal for further information you might need.

Best Regards,

Michele Capelli