



To All Lamborghini dealers and Service Points

From Commercial Department : After Sales - Spare Parts
Pages 2
Object **Service campaign ref.:L147.A.-01.03
ashtray**
Date 05.06.2003

Automobili
Lamborghini S.p.A.

Dear Sirs,

service campaigns are meant to keep an high quality level of the product.

Therefore, we send you the instruction to carry out the service campaign mentioned above.

Description:

Ashtray has a new way of opening

Vehicles involved:

Murciélago: from VIN **ZA9BC10__2LA12026** to VIN **ZA9BC10__2LA12331**

Murciélago: from VIN **ZA9BC10__3LA12332** to VIN **ZA9BC10__3LA12608**

Murciélago: from VIN **ZHWB_16__3LA00610** to VIN **ZHWB_16__3LA00619**

Technical information:

The action refers to Murciélago having the chassis numbers listed here on top.

Solution:

Changing the old ashtray with the new one as explained in the attached procedure:

L147-A.01.03.

Network information:

All Lamborghini dealers will be informed of this action.

Via Modena,12
I-40019 Sant'Agata
Bolognese
Telefono +39 051-6817 7:
Telefax +39 051-6817 7:



Parts for vehicle :

p/n 0059014631 1 pz

Parts supply:

Lamborghini will send the component on request by standard procedure.

Replaced material:

No need to return any parts.

Warranty refund:


To have the refund, the dealer has to send back the usual warranty claim duly filled in with the following information:

Problem description:	service campaign L147.A-01.03
Cost code :	50
Component code:	78118
Problem code:	220
Labour code:	78106106
Time:	1

Please attach to the warranty manual the sticker p/n 901475000 filled with campaign details.

For any further information you may need please contact your Area Manager.

Best regards,


Giorgio Gamberini
After Sales Manager


Michele Capelli
Training & Publications



Procedure L147.A-01.03
Operation: ashtray change

- 1.1 Disassemble the ashtray in the tunnel
- 1.2 Take the ashtray box away
- 1.3 Take the pin (on the side of the tooth wheel) and the correspondent spring away, (old ashtray) , picture 1



picture1

- 1.4 Disassemble the ashtray lid from its housing, (old ashtray), picture 2



picture 2

- 1.5 Disassemble the ashtray lid (new ashtray), repeat fro the new ashtray the steps 1.1 to 1.3
- 1.6 Mount the old ashtray lid (covered by leather) in the housing of the new ashtray , **without mounting the spring**, picture 3



picture 3

1.7 Mount the new ashtray with the old lid on the vehicle