



Phone +39.051.6817652
Fax +39.051.6817738

To : All Lamborghini Dealers

From : After Sales Department

Date: 11 October 2002

Pg: 2

SERVICE CAMPAIGN ref.: L147.A-01.02

BRACKETS FOR MUFFLER HOOD

Dear Dealer,
service campaigns are meant to keep an high quality level of the product.
Therefore, we send you the instruction to carry out the service campaign
mentioned above.
**The control will have to be carried over as soon as one of the vehicles listed below
is by your workshop for any other reason.**

Description:
Brackets for muffler hood.

Vehicles involved:
See attached file: L147.A-01.02 VIN numbers.

Technical Information
The action refers to Murciélago having the chassis numbers listed in the
attachment.

Solution
Component replacement as for attached procedure: L147.A-01.02 Quality Control
and Procedure.

Network information:
All authorized Lamborghini dealers will be informed of this action.

Parts for vehicle
One or two brackets depending on necessity.

Parts supply
The part (p/n 73010713/14) has to be ordered to Lamborghini Spare Parts Dpt.
following the existing procedures.



Phone +39.051.6817652
Fax +39.051.6817738

Replaced material

The replaced material has to be returned along with the specific tag as for all the warranty returned material (see "Warranty and procedure manual", chapter 6).

Warranty refund

To have the refund, the dealer has to fill the usual warranty claim and send it to the Warranty dpt. with the following information:

Problem description:	service campaign L147.A-01.02.
Cost code:	50
Component code:	73104
Problem code:	220
Labour code:	73104103

Time for replacement:	1h
------------------------------	-----------

Please attach to the warranty manual the sticker p/n 901475000 filled with campaign details.

For any further information you may need please contact your Area Manager.

Best regards