



To All Authorized Lamborghini Dealers & Service Points  
From Customer Service Department  
Subject Seven switch console replacement  
Group 08.57.00  
Date 23/07/10  
Pages 6

### Subject

Replacement of seven switch console

### Model

All Lamborghini Gallardo Coupe and Spyder (version LP560) MY 2009 and 2010 from VIN 9LA06526 to VIN ALA09101.

**Warning:** some vehicles included in this VIN range may not be affected, so check carefully on the Lamborghini WEB Portal (at the VIN Info section) whether the cars in your workshop or in your eventual stock are affected before performing any other operation.

### Information to the field

As a continuous product monitoring, Automobili Lamborghini Spa has found that the power window switches located in the central consoles may have difficulty in operating.

### Field solution

Replacement of the seven switch console.

### Spare Parts

a. For left hand drive version (LHD) vehicles:

P/N	Description	Q
401941567D	7 switch console	1

b. For right hand drive (RHD) Vehicles::

P/N	Description	Q
402941567D	7 switch console	1

### How to manage the replaced seven switch console

The replaced seven switch consoles have to be stored with care and each piece tagged with the proper label. The parts can be scrapped after the approval of the Service Area Manager.

---

*The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A, as per copyright law. The company reserves the right to make revisions and modifications. The following are prohibited: reprinting, reproduction, forwarding to unauthorized persons and/or third parties, and either partial or complete translation, without the express written consent of Automobili Lamborghini S.p.A.*



## Warranty Claim data




The warranty reimbursement request for this rework action will be managed by the following standard Warranty Claim procedures.

**Campaign Code:** L714-A02.10 ; L715-A02.10  
**Campaign Description:** 7 switch console replacement  
**Cost Code:** 50  
**Component Code:** CCA0210  
**Trouble Code:** 220  
**Labour Code:** CCA0210100  
**Labour Time:** 0,10 h


Automobili Lamborghini S.p.A.			
Campagne service assistenza e campagne di richiamo / Service-und Rückrufaktion / Service and Recall Campaign Service et campagne de rappel / Campaña de Servicio y Llamada a Taller			
Service/Service Servizio	<input type="checkbox"/>	Richiamo/Rückruf Recall/Rappel Llamada a Taller	<input type="checkbox"/>
Numero/Nummer Number/Numéro Número	<input type="text"/>		
Data/Datum/Date/Date/Fecha	<input type="text"/>		
Data riparazione/Reparaturdatum Repair Data/Date de réparation Fecha reparación	<input type="text"/>		
Eseguito dal Concessionario / Ausgeführt von der Vertragswerkstatt / Done by the Dealer Effectué par le concessionnaire / Efectuado por el Concessionario			
Firma / Unterschrift / Signature / Signature / Firma			
Service/Service Servizio	<input type="checkbox"/>	Richiamo/Rückruf Recall/Rappel Llamada a Taller	<input type="checkbox"/>
Numero/Nummer Number/Numéro Número	<input type="text"/>		
Data/Datum/Date/Date/Fecha	<input type="text"/>		
Data riparazione/Reparaturdatum Repair Data/Date de réparation Fecha reparación	<input type="text"/>		
Eseguito dal Concessionario / Ausgeführt von der Vertragswerkstatt / Done by the Dealer Effectué par le concessionnaire / Efectuado por el Concessionario			
Firma / Unterschrift / Signature / Signature / Firma			

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A, as per copyright law. The company reserves the right to make revisions and modifications. The following are prohibited: reprinting, reproduction, forwarding to unauthorized persons and/or third parties, and either partial or complete translation, without the express written consent of Automobili Lamborghini S.p.A.


## Disassembling

1	<b>WARNING!</b> <b>Always take the utmost care not to damage the interior upholstery</b>	
2	Lift the seven switch console and remove it from its housing  <b>WARNING !</b> <b>Always take the utmost care not to damage the interior upholstery</b>	
3	Pull out the seven switch console until the two lateral slots are removed from their guides on the instrument panel.	
4	Disconnect the electrical connector.	



*The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A, as per copyright law. The company reserves the right to make revisions and modifications. The following are prohibited: reprinting, reproduction, forwarding to unauthorized persons and/or third parties, and either partial or complete translation, without the express written consent of Automobili Lamborghini S.p.A.*

5	Remove the seven switch console.	
---	----------------------------------	--

### Assembly

6	<b>WARNING!!!</b> <b>When performing the following operations, take the utmost care not to damage or ruin the interior upholstery.</b>	
7	Connect the electrical connector.	

*The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A, as per copyright law. The company reserves the right to make revisions and modifications. The following are prohibited: reprinting, reproduction, forwarding to unauthorized persons and/or third parties, and either partial or complete translation, without the express written consent of Automobili Lamborghini S.p.A.*

8	<p>Install the seven switch console. Be sure the two lateral slots are inserted into their guides on the instrument panel.</p>	
9	<p>Align the seven switch console with the other items on the instrument panel.</p> <p><b>WARNING!!!</b> Do not damage the interior upholstery.</p>	

Please contact your Area Manager for any further information.

Yours sincerely,

Customer Service.

*The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A, as per copyright law. The company reserves the right to make revisions and modifications. The following are prohibited: reprinting, reproduction, forwarding to unauthorized persons and/or third parties, and either partial or complete translation, without the express written consent of Automobili Lamborghini S.p.A.*