



To All Lamborghini Dealers and Licensed Service Point  
From Customer Service Department  
Subject Oil level dipstick & sticker  
Group LB824.01.17  
Attachments -  
Date 20/07/2007  
Pages 6

## Subject

New oil level dipstick & sticker

Automobili  
Lamborghini  
S.p.A.

## Model / VIN-Range

MY 07 Murciélago LP640 (Coupè and Roadster) from VIN B71805 to VIN B72615.

Attention: As not all cars from this VIN range are affected, please carefully check on the Lamborghini Web-portal to verify the VIN-Info and if the car is affected by this service campaign before the start of any activity.

## Information to the field

We found that the oil checking level for Murciélago LP640 is not easily repeatable and it is possible that the level seems lower than in reality during the PDI inspection.

To avoid unnecessary oil adding that could also damage the catalyst system please use the attached new procedure for the oil level checking and replace the old oil level dipstick with the new one.

## Field solution

Every dealer should order to the spare parts department the new rework kit that contains the oil level dipstick, the new sticker for the engine compartment and the corrective page for the owner's manual.

## Spare Parts

Is necessary one repair kit per car. The oil level dipstick is different between Roadster and Coupè, the two kit are:

- 0R1470056 Murciélago Roadster
- 0R1470055 Murciélago Coupè

The order must be sent with the indication of the car VIN using RIU procedure (urgent parts ordering).

---

*The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.*

Via Modena,12  
I-40019 Sant'Agata  
Bolognese  
Tel +39 051 6817 652  
Fax +39 051-6817 709



## Warranty Claim data

The warranty reimbursement request for this rework action will be managed by the following standard Warranty Claim procedure.

**Campaign Code:** L824-A.01.07 (Coupè) / L825-A.01.07 (Roadster)  
**Campaign Description:** Oil level dipstick & sticker  
**Cost Code:** 50  
**Component Code:** CCA0107  
**Trouble Code:** 220  
**Labour Code:** CCA0107100  
**Labour Time:** 0,25 h

The spare part kit contains:

- One oil level dipstick (Picture 1 for Coupè and 2 for Roadster)
- One sticker for the engine compartment (Picture 3)
- One new page for the user manual (attachment at the end of this document)

Pict. 1

Oil dipstick  
Murciélago  
Lp640 Coupè



07M 115 311 D

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.



Pict 2

Oil dipstick  
Murciélago  
Lp640 Roadster



07M 115 311 C

Pict. 3 Sticker for the engine compartment 07M 115 562 B

controllo livello olio motore

verifica a temperatura olio 80° +/- 10°C  
motore in moto, con olio caldo, per almeno 5 min.  
motore al minimo per 60s  
spegnere motore ed eseguire il controllo entro 30s

engine oil level check

check at oil temperature 80° +/- 10°C  
engine started since 5 minutes  
engine at idle 60 seconds  
switch off the engine and check level within 30 seconds






## Workshop instruction:

- 1.1 Adopt all precautions to prevent car damages and to work safe.
- 1.2 Replace the old dipstick and the sticker as shown in picture 4 with the new ones. The dipstick code is written under the cap as shown in picture 5.
- 1.3 Add the corrective page for the User Manual booklet as indicated below:
  - pag. 135 for Coupè USA & Canadian market
  - pag. 105 for Coupè European and Rest of the World market
  - pag. 153 for Roadster USA & Canadian market
  - pag. 121 for Roadster European and Rest of the World market

Pict. 4



Pict. 5





## Oil level checking procedure

- 1.4 The oil level check must be carried out when the engine is hot, with an oil temperature between 70 and 90°C.
- 1.5 Bring the engine to idle speed and keep it there for 5 minutes to avoid every strategy that can bring the engine to run higher after a start up.
- 1.6 Be sure that the engine runs to the nominal idle speed (960 rpm  $\pm$  50 rpm) and keep it there for 60 seconds.
- 1.7 Turn off the engine.
- 1.8 Check the oil level within 30 seconds after turning off the engine.
- 1.9 **The level with new oil dipstick (07M115311C & 07M115311D) should be between ( $\pm$  5 mm) the MIN and MAX marks.**
- 1.10 The difference in the amount of oil between the level corresponding to min and max marks is about 1,4 L.

Your Area Manager is at full disposal for further information.

Best regards

Customer Service