

TECHNICAL BULLETIN
LTB00581NAS1
16 SEP 2013



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 204-05

Front Air Spring - Lower-Level Repair Kit

AFFECTED VEHICLE RANGE:

Range Rover (LM)

Model Year: 2003-2012

VIN: 3A101029-CA393639

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A lower-level service repair kit is now available in the event it is necessary to replace the front air spring while the shock absorber is still functional.

Cause: Front air spring replacement.

Action: Should a customer express this issue, follow the Service Instruction outlined below.

PARTS:

LR051702	Air spring repair kit - Front left	Quantity: 1
LR051700	Air spring repair kit - Front right	Quantity: 1

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

 **NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Air spring - one side - renew (front)	60.21.07	1.1	D1	LR032560
Air spring - both sides - renew (front)	60.21.08	2.0	D1	LR032560

 **NOTE: Normal Warranty policies and procedures apply.**

SERVICE INSTRUCTION:

1. Install new front air spring(s) (see TOPIx Workshop Manual, Section 204-05: Vehicle Dynamic Suspension Front Air Spring).