



Service Bulletin

PRELIMINARY INFORMATION

Subject: Adding Cruise Control (RPO K34)

Models: 2007 - 2013 Chevrolet Silverado
2007 - 2013 GMC Sierra

This PI was superseded to include Warranty Information. Please discard PIT4844C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may request the installation of Cruise Control on a vehicle which did not come equipped with the option. General Motors requests that dealers locate a vehicle equipped with the customers requested options, which would include cruise control.

Recommendation/Instructions

If, however, a customer purchased the vehicle with the promise of having this option installed, please contact the Techline Customer Support Center (TCSC) at 1-800-828-6860 to see if a calibration is available for the vehicle. If a calibration or VCI is available, follow the instructions below:

Obtain and install the following parts that are intended for a vehicle equipped with RPO K34.

1. Steering Wheel with Cruise Control Buttons
2. Steering Wheel SIR Coil
3. Steering Column Wiring Harness
4. Calibration or VCI number from Techline Customer Support

Note: It is up to the dealer to identify the appropriate part numbers needed to complete this add on option using the Electronic Parts Catalog (EPC). Be sure to turn off all filters when searching EPC and identify the following items above that include RPO K34. DO NOT call Partech for parts assistance for this request.

Warranty Information

This installation procedure is to be performed at the customer's request and at their expense. It is not a warranty repair and a claim should not be submitted for reimbursement.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION