



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** 5th Wheel Or Camper Wiring Harness Location

**Models:** 2015-2016 Chevrolet Silverado  
2015-2016 GMC Sierra  
With 5th Wheel / Camper Harness (RPO UY2)


*This PI was superseded to update the Models section. Please discard PIT5273.*

### Condition/Concern

Some owners may question where the blunt cut wires are located for the gooseneck / 5th wheel / camper wiring harness (vehicles equipped with RPO UY2).

On past models, this harness was located along the left frame rail near the front of the pickup box.

Starting with the 2015 model year, the location has changed to the rear of the pickup box – forward of the rear bumper and attached to the rear frame cross member, as shown below. NOTE: Picture below was taken with the pickup box removed.



GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION