



# Preliminary Information

PIP5240D Mil On With DTC P0171 And / Or P1101

## Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2013 - 2018	All	All	1.4L (LUV) (LE2)	All
Chevrolet	Trax	2013 - 2018	All	All	1.4L (LUV) (LE2)	All

## Supersession Statement

This PI was superseded to update Model Years. Please discard PIP524C.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

## Condition / Concern

A technician may encounter a DTC P0171 And / Or P1101 set current or in history.


## Recommendations / Instructions

If current SI diagnostics do not isolate the cause of the concern, inspect the Air Cleaner Housing for proper content as shown.


If the air cleaner housing does not have the proper content for the engine application as shown, replace the Air Cleaner Housing with the latest part listed in the Electronic Parts Catalog.

If the vehicle is equipped with the proper content, refer back to SI diagnostics.

- LE2 has both HCA and Diffuser



- LUV has ONLY HCA



Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



© 2016 General Motors. All Rights Reserved.