



Preliminary Information

PIT5420D Water Rush Or Gurgle Noise From Heater Core

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2015 - 2017	All	All	LCV	All
GMC	Canyon	2015 - 2017	All	All	LCV	All
Involved Region or Country:		North America				
Additional RPO/s:						
Condition:		The customer may note a water rush or gurgle type noise from the center dash area. The technician may isolate this noise to the heater core caused by air in the cooling system.				
Cause:		Air ingestion in the cooling system, under evaluation by engineering.				

Correction:

Pending release of new surge bottle.

Recommendations / Instructions

TEST

Version History

Version	4.0
Modified	

