

Service Bulletin

File in Section: 08 - Body and Accessories

Bulletin No.: 12-08-132-001B

Date: May, 2014

INFORMATION

Subject: Accessory Power Outlet and Trailer Lighting Fuse Replacement — Use Global Labor

Operation 5430130 Fuse Replacement

Models: 2011-2015 GM Passenger Cars and Trucks

This bulletin has been revised to remove Model Year 2010 vehicles, add Model Year 2015 vehicles, update the Subject with the new GLC 5430130 and change the term warranty claim to Warranty Transaction. Please discard Corporate Bulletin Number 12-08-132-001A.

Accessory Power Outlet and Trailer Lighting Fuse Replacement Customer Enthusiasm Information

Accessory Power Outlets (APO) and Trailer lighting are the most commonly accessed electrical systems that can be affected by devices that are plugged in by the customer.

If a vehicle is encountered with one of these systems being inoperative due to an open fuse, and a problem cannot be identified with the vehicle, it is reasonable to suspect that something the customer may have plugged into the APO or the trailer connector may have caused the fuse to open. For vehicles repaired under the Bumper-to-Bumper Coverage, in Canada, Base Warranty Coverage, when a defect in material or workmanship cannot be identified and the dealership still wants to cover the fuse replacement under warranty, this type of Warranty Transaction must be entered as: **Customer Enthusiasm**.

Identifying these types of repairs as Customer Enthusiasm helps engineering to focus their resources on product issues they need to address.

For complete instructions on how to submit a Customer Enthusiasm Warranty Transaction, refer to the latest version of Corporate Bulletin Number #11-00-89-005: Clarification of Use - Dealer Empowerment Labor Operations and Customer Enthusiasm (U.S. Only).

GM of Canada dealers should refer to the Goodwill section on the Warranty Administration Homepage in GM GlobalConnect.

