



Preliminary Information

PIC6354 Auxiliary Coolant Pump Noise Heard During an Autostop Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Regal	2018	All	All	All	All

Involved Region or Country	North America
Condition	A customer may notice a pump type noise heard when the vehicle is in an autostop event.
Cause	The ECM can command the auxiliary coolant pump during an autostop to aid in maintaining the heater (HVAC) performance.

Correction:

Do not replace any parts, the pump is working as designed.

Note: This PI may be converted into a bulletin when new information is available.

Version History

Version	1
Modified	03/12/2019 - Created on

