



## Preliminary Information

### PIC4782A HHR Panel Van Key Fobs Missing Panel Buttons

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	HHR Panel Van	2007 - 2011	All	All	All	All

#### Supersession Statement

This PI was superseded to update Model Years. Please discard PIC4782.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition / Concern

A customer may comment that the key fobs for his or her 2007 HHR Panel van DO NOT have the rear cargo/access door buttons. This is correct for that particular model year vehicle. ONLY the 2008 and newer model year HHR Panel Van key fobs come with rear access panel door buttons. See the photo below for a picture of the two different transmitters.



1) 2008 - 2011 HHR Panel Van transmitter

2) 2007 HHR Panel Van transmitter

#### Recommendations / Instructions

##### **By design:**

##### **For 2007:**

**HHR Panel Vans do NOT have rear cargo door buttons on the key fobs.**

##### **For 2008 - 2011:**

**HHR Panel Vans DO have the rear cargo door buttons on the key fobs.**

**NOTE: The older 2007 system can NOT be upgraded to the newer 2008+ system.**

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.