



Preliminary Information

PIT5667 Diagnostic Aid: C0460 Stored after Service

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2017 - 2019	All	All	All	All

Involved Region or Country:	North America
Condition:	C0460 stored after service.
Cause:	Loss of volatile memory.

Correction:

If the battery is disconnected for service this code will set current. After service is completed it is necessary to either turn the steering wheel from lock to lock with the engine running or to drive the vehicle in a straight line to allow the PSCM to re-zero the SAS. If the intermediate steering shaft has been removed for service and this code will not clear, verify the shaft is properly indexed when installed. This may become a bulletin as more information becomes available.

Version History

Version	1
Created	03/29/2019 - Created on

