



Bulletin No.: PIC6354A  
Published date: 05/6/2019

# Preliminary Information

## PIC6354A Auxiliary Coolant Pump Noise Heard During an Autostop

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Regal	2018 - 2019	All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	A customer may notice a pump type noise heard when the vehicle is in an autostop event.
<b>Cause</b>	The ECM can command the auxiliary coolant pump during an autostop to aid in maintaining the heater (HVAC) performance.

**Correction:**

Do not replace any parts, the pump is working as designed.

**Note: This PI may be converted into a bulletin when new information is available.**

Version History

Version	2
Modified	03/12/2019 - Created on. 05/05/2019 - Updated Model Years.



GENERAL MOTORS