

Parts Bulletin

TITLE:

Extended Warranty P29929: Low Pressure Fuel Sensor Model Year 2015 - 2016 S60, V60, XC60, S80, XC90, XC70

GROUP:	CAT/NO: P29929	REFERENCE BULLETINS: QB P29929		CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):				ISSUE DATE:	STATUS DATE:
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	2019-05-23	2019-05-23
				Page 1 of 1	

"Right first time in Time"

Reference Bulletins: QB P29929

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Corporation, has voluntarily decided to extend warranty coverage on certain model year 2015 – 2016 S60, V60, XC60, S80, XC90, XC70 models. Volvo has determined that there is the potential for the wire bonding inside the Low Pressure Fuel Sensor (LPS) to become damaged over time. This condition can illuminate the Check Engine Lamp in the Driver Information Module with Diagnostic Trouble Code (DTC) ECM-P018C00.

The corrective action is to replace the Low Pressure Fuel Sensor per VIDA instructions, if the vehicle displays the condition listed in this bulletin.

For eligible vehicles that are beyond the manufacturer warranty period, <u>Volvo will extend the warranty coverage for the Low Pressure Fuel Sensor for 8 years or 80,000 miles from the original vehicle in service date</u>. Coverage is limited to the symptoms described in this bulletin for the Low Pressure Fuel Sensor only.

The 8 year extended warranty only applies to vehicles which have exceeded the 4 year or 50,000 miles / 80,000 kilometers New Vehicle Warranty by time or mileage.

The limitations and conditions for this extended warranty are identical to the Volvo New Vehicle Warranty. Please refer to the Warranty and Maintenance Records Information booklet for details.

The following part numbers apply:

Part Number	Description	Qty	
32242867	Low Pressure Fuel Sensor	1	S/V/XC60, XC70, S80
32242869	Low Pressure Fuel Sensor	1	XC90