



Service Bulletin


Bulletin No.: 19-NA-126


Date: June, 2019

INFORMATION

Subject: Emergency Trunk Release Key Will Not Turn, Unable to Open Trunk from Lock Cylinder Behind Rear Seat Back, Information on Convertible Key Extender

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Camaro - Convertible	2016	2019			All	All

Involved Region or Country	North America, South America, China, Japan, Middle East, Israel
Condition	 <p style="text-align: right;">5338393</p> <p>Some customers may comment that they have difficulty turning the key in the emergency trunk release cylinder, located behind the upper, center of the rear seatback cushion.</p>

<p>Information</p>	 <p style="text-align: right;">5338396</p> <p>All convertibles come with a key extender packaged in with the loose shipped items from the assembly plant. The key extender should be placed in the glove box at the time of PDI.</p>
<p>Correction</p>	<p>Caution: Failure to use the key extender could cause the key to twist and break in the cylinder.</p> <p>The key extender should be used when opening the trunk, from the lock cylinder located behind the rear seat back cushion.</p> <p>Additional information regarding the proper usage of the key extender can be found in the Emergency Trunk Release (Convertible Only) section of <i>Trunk</i> in the Owner Manual.</p>

Parts Information

Causal Part	Description	Part Number	Qty
N/A	Cover, Door Lock Key (Key Extender)	84076489	1

Version	1
Modified	Released June 06, 2019

