

SERVICE MANUAL BULLETIN

This Service Manual Bulletin is prepared by the Publications Department of New Flyer Industries Canada ULC. Refer to details below.

SMB-185

ISSUE DATE: Jun 21 2019

APPLICABILITY	
VEHICLE LENGTH	<input type="checkbox"/> 30ft. <input checked="" type="checkbox"/> 35ft. <input checked="" type="checkbox"/> 40ft. <input checked="" type="checkbox"/> 60ft. <input type="checkbox"/> ALL
VEHICLE TYPE	<input checked="" type="checkbox"/> Xcelsior® <input type="checkbox"/> MiDi® <input type="checkbox"/> Invero® <input type="checkbox"/> Low Floor <input type="checkbox"/> High Floor <input type="checkbox"/> ALL
FUEL TYPE	<input type="checkbox"/> Diesel <input type="checkbox"/> Diesel/Electric <input type="checkbox"/> CNG <input type="checkbox"/> LNG <input type="checkbox"/> Fuel Cell <input type="checkbox"/> Trolley/Electric <input checked="" type="checkbox"/> Battery/Electric <input type="checkbox"/> ALL
SUBJECT	ESS Battery Coolant Filter Replacement
SECTION TITLE	PM - Preventive Maintenance, Two Year Preventive Maintenance
DETAILS	<p>This bulletin revises the lubrication step in the replacement procedure of the Coolant Filter installed on your New Flyer vehicle.</p> <p>Lubricate the gasket and threads on the new filter with clean DEX III transmission fluid and install by hand.</p> <p>This information supersedes any prior information on this subject already provided in your New Flyer Service Manuals. Make this Service Bulletin available to service personnel to inform them of changed information.</p>

