

**ATTENTION:**  
 GENERAL MANAGER   
 PARTS MANAGER   
 CLAIMS PERSONNEL   
 SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

|  |  |  |  |  |  |
|--|--|--|--|--|--|
|  |  |  |  |  |  |
|  |  |  |  |  |  |

© 2020 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

**SERVICE INFORMATION BULLETIN**

**APPLICABILITY:** 2017-18MY Impreza  
 2018MY Crosstrek  
 2019MY Forester  
 2019MY Ascent

**NUMBER:** 11-196-20  
**DATE:** 01/31/20

**SUBJECT:** PCV Valve Part Information

**INTRODUCTION:**

This Service Information Bulletin announces part number change information for the Positive Crankcase Ventilation (PCV) valves used on the models listed above.

**PART INFORMATION:**

| Description            | NEW Part Numbers | Application         | OLD Part Numbers | Interchangeability  |
|------------------------|------------------|---------------------|------------------|---|
| VALVE COMPLETE CONTROL | 11810AA190       | Impreza & Crosstrek | 11810AA150       | New Parts to Old Vehicles: <b>YES</b> .<br>Old Parts to New Vehicles: <b>NO</b> . |
|                        | 11810AA200       | Forester            | 11810AA180       |   |
|                        | 11810AA210       | Ascent              | 11810AA170       |   |

**NOTES:**

- For **Impreza and Crosstrek**, the new PCV part number above is the same as the PCV included in the p.n. X1181AA000 PCV kit specified for the WUP-01R Campaign Bulletin.
- For **Ascent**, the new PCV part number above is the same as the PCV included in the p.n. X1181AA010 PCV kit specified for the WUW-08R Campaign Bulletin.
- All the new PCV part numbers listed above are made of steel instead of aluminum.  
**REMINDER:** Always order the most up-to-date replacement parts based on the specific VIN being repaired.

**SERVICE PROCEDURE / INFORMATION:**

**REMINDER:** Customer satisfaction and retention starts with performing quality repairs.

|  |   |
|--|---|
| <p><b>CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.</b></p> <p>Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.</p> | <p>Subaru of America, Inc. is ISO 14001 Compliant</p> <p>ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.</p> |
|--|---|

*Continued...*

The service procedures for PCV Valve replacement remain unchanged. Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time and every time. This includes but is not limited to: important SAFETY precautions, proper inspection criteria, necessary special tools, processes and one-time-use parts needed for a complete and lasting repair.

**IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.