



Bulletin No.: PIP5677D

Published date: N/A

Preliminary Information

PIP5677D 2021 10L60 10L80 10L90 10 Speed Gen II Automatic Transmission Restriction Program

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2021	All	All	All	MQA
Cadillac	CT5	2021	All	All	All	MHS
Chevrolet	Camaro	2021	All	All	All	MI1

Involved Region or Country	North America
Condition	Transmission Assembly
Cause	Restriction

Correction:

The 10L60, 10L80 and 10L90 10 Speed Automatic Transmission part numbers 24042586, 24269983, 24269984, 24271644, 24271645, 24278968, 24278969, 24284098, 24284099, 24284102, 24284121, 24289388, 24290455, 24290456, 24291499, 24291500, 24291503, 24294947, 24294948, 24294949, 24294950, 24294951, 24294952, 24295019, 24295020 and 24295021 are on restriction through GM PQC as part of our ongoing quality improvement efforts to assist Engineering with product concern identification effective on 09/24/19.

Your cooperation with this program is greatly appreciated.

Note: Do not disassemble the transmission or clear any DTCs prior to contacting Product Quality Center.

If your diagnosis has led to an internal repair or replacement of the 10L60, 10L80 or 10L90 10 Speed Automatic Transmission, please contact the Product Quality Center (PQC) by opening a case via Dealer Case Management (DCM) From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Then, in Global Connect click on the Support/Chat tab, TAC-PQC Tab, PQC -Parts Restrictions Templates to Download the appropriate PQC -Parts Restrictions Template and save a copy to your computer, You can attach a copy of the template to your PQC Case.

Parts Information

Description	Part Number	QTY
Transmission Assembly	24042586	1
Transmission Assembly	24269983	1
Transmission Assembly	24269984	1
Transmission Assembly	24271644	1
Transmission Assembly	24271645	1
Transmission Assembly	24278968	1
Transmission Assembly	24278969	1
Transmission Assembly	24284098	1
Transmission Assembly	24284099	1

Transmission Assembly	24284102	1
Transmission Assembly	24284121	1
Transmission Assembly	24289388	1
Transmission Assembly	24290455	1
Transmission Assembly	24290456	1
Transmission Assembly	24291499	1
Transmission Assembly	24291500	1
Transmission Assembly	24291503	1
Transmission Assembly	24294947	1
Transmission Assembly	24294948	1
Transmission Assembly	24294949	1
Transmission Assembly	24294950	1
Transmission Assembly	24294951	1
Transmission Assembly	24294952	1
Transmission Assembly	24295019	1
Transmission Assembly	24295020	1
Transmission Assembly	24295021	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8464670	Transmission Replacement	Use Published Labor Operation Time

Version History

Version	5
Modified	<p>09/23/2019 - Created on.</p> <p>10/02/2019 - Added transmission part numbers 24269983, 24269984, 24282946, 24284102, 24284121, 24289388 and 24294934. Added the 2019 model year.</p> <p>02/04/2020 - Removed the 2019 model year and transmission part number 24290680.</p> <p>02/18/2020 - Removed transmission part numbers 24268797, 24269986, 24271649, 24274314, 24281547, 24282946, 24289388, 24290680, 24291506, 24291507, 24294934 and 24298121. Added transmission part numbers 24042586 and 24284098. Removed models and added the 2019 model year.</p> <p>11/17/2020 - Removed the 2019 and 2020 model years and added the model year 2021. Added the 2021 Chevrolet Camaro. Added transmission part numbers 24294947, 24294948, 24294949, 24294950, 24294951, 24294952, 24295019, 24295020, 24295021. Removed the PQC questionnaire.</p>

