

Subject: Engineering Information - Service Engine Soon Lamp Illuminated, DTCs P0494, P2CB9, U0632 and/or U0633 Set

This PI has been revised to end the need for information from the field. Please discard PIE0601.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	Escalade Models	2021	2021	-	-	Applies to ALL Engines	-
Chevrolet	Silverado 1500	2020	2020			Applies to ALL Engines EXCEPT 3.0L (RPO LM2)	
	Silverado 1500	2021	2021			Applies to ALL Engines	
	Suburban						
	Tahoe						
GMC	Sierra 1500	2020	2020			Applies to ALL Engines EXCEPT 3.0L (RPO LM2)	
	Sierra 1500	2021	2021			Applies to ALL Engines	
	Yukon Models						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released November 25, 2020 Revised December 22, 2020 – Ended the need for further information from the field.