

**ATTENTION:**

GENERAL MANAGER ☐

PARTS MANAGER ☐

CLAIMS PERSONNEL ☐

SERVICE MANAGER ☐

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.


© 2021 Subaru of America, Inc. All rights reserved.



**SUBARU**

QUALITY DRIVEN® SERVICE

## SERVICE BULLETIN

**APPLICABILITY:** 2022MY Outback Wilderness

**NUMBER:** 16-134-21

**DATE:** 10/05/21

**SUBJECT:** DTC #P0871 Transmission Pressure Sensor/  
Switch "C" Circuit Range/Performance -  
Diagnostic Information

### INTRODUCTION:

This Service Information Bulletin announces additional diagnostic information concerning DTC #P0871. The information provided below is to be used together with the applicable Service Manual to streamline the diagnosis process for DTC #P0871 and help prevent any misdiagnosis.

### SERVICE PROCEDURE / INFORMATION:

**REMINDER:** Customer satisfaction and retention starts with performing quality repairs.

Always refer to the applicable Service Manual and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time, every time. This includes but is not limited to important SAFETY precautions, proper inspection criteria, necessary special tools, required processes and related one-time-use parts needed for a complete and lasting repair. DTC #P0871 can be set due to internal misdiagnosis of the TCM. Use the flow chart below to distinguish the fault characteristic.

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**


Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

*Continued...*

## Flow Chart for DTC: P0871:



Continued...

**IMPORTANT REMINDERS:**

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.