



Bulletin No.: PIP5871
Published date: 09/9/2022

Preliminary Information

PIP5871 DTC P11D5 Calibration Update

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2023	All	All	6.6L (L5P)	All
GMC	Sierra 2500/3500	2023	All	All	6.6L (L5P)	All

Involved Region or Country	North America
Condition	Customer may complain of a MIL on DIC
Cause	A technician may see P11D5 set in the ECM

Correction:

This may be caused by a software anomaly.

Please check for a ECM update.

If none is available, refer to Service Information.

Additional SI Keywords

cal, Nox,

Version History

Version	1
Modified	9-9-2022 - Created.



© 2022 General Motors. All Rights Reserved.