



Bulletin No.: PIC6473
Published date: 09/19/2022

Preliminary Information

PIC6473 Paint Missing From Inside Flange of Wheels

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	PJA - WHEEL-22 X 9.5 ALUMINUM
Condition	Paint missing from inside flange of wheels
Cause	Manufacturing process





Correction:

None, there is no need to replace the wheels for this condition, it will not affect the durability of the wheels.

Note: Some wheels may have more paint missing than the picture shown.

Version History

Version	1
Modified	09/19/2022 - Created on.



© 2022 General Motors. All Rights Reserved.