

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2013MY Legacy and Outback
 with a Backup Camera

NUMBER: 15-156-12R

DATE: 08/20/12

REVISED: 04/04/13

SUBJECT: Deletion of Compass Mirror

INTRODUCTION

2013 Model Year Outback and Legacy vehicles equipped with a backup camera no longer have a compass feature available in the factory installed auto-dimming mirror. In the event a customer requires a compass feature in an auto-dimming mirror, the factory installed mirror on some trim levels may be replaced with an auto-dimming compass mirror with HomeLink. This mirror is different from our standard accessory mirror offered for 2013 Outback and Legacy vehicles. Please reference the following chart for applicability and part numbers. Installation of the HomeLink mirror should be treated as any other accessory installation request by the customer and is not a matter for warranty.

Warning: There is no accessory mirror that can be installed **in** vehicles equipped with EyeSight. The OE mirror on an EyeSight vehicle should not be modified or extended.

APPLICABILITY AND REPLACEMENT PART INFORMATION

MODEL	TRIM	DESCRIPTION	REPLACEMENT PART
Outback	2.5i Premium	All-Weather Package + Moonroof Package	92021AJ10A**
	2.5i Premium	All-Weather Package + harmon/kardon® Audio System + Moonroof Package	H501SXA201
	2.5i Limited	Moonroof Package	H501SXA201
	2.5i Limited	Moonroof + Navigation System	H501SXA201
	2.5i Limited	Special Appearance Package	H501SXA201
	3.6R Limited	Moonroof Package	H501SXA201
	3.6R Limited	Moonroof + Navigation System	H501SXA201
	3.6R Limited	Special Appearance Package	H501SXA201

** Part number 92021AJ10A **is** equipped with a backup camera display.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS "ISO 14001 COMPLIANT"

The international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

MODEL	TRIM	DESCRIPTION	REPLACEMENT PART
Legacy	2.5i Limited	Moonroof + Navigation System	H501SXA201
	3.6R Limited	Moonroof + Navigation System	H501SXA201

INSTALLATION INFORMATION

For mirror installation, remove the OE mirror by first disconnecting the wire harness from the back of the mirror. Loosen the Torx® screw then slide the mirror upward and off of the windshield mirror mount.

Install the replacement mirror by sliding it down onto the windshield mirror mount. Then tighten the Torx screw to 13.3 – 17.7 in-lbs., and re-connect the wire harness to the back of the mirror.



Auto-Dimming Compass Mirror with HomeLink