



SERVICE BULLETIN

Classification: EM02-003	Reference: NTB02-050	Date: April 23, 2002
-----------------------------	-------------------------	-------------------------

VQ ENGINE WATER PUMP O-RING

APPLIED VEHICLES: 2002 Pathfinder (R50)
2002 Maxima (A33)
2002 Altima (L31)

APPLIED DATE: See Figure 1 below

APPLIED ENGINE: VQ35DE

SERVICE INFORMATION

If, for any reason, the water pump needs to be serviced, please note that:

- The front O-ring (on the water pump) has changed
- The new O-ring is now black with a white paint mark instead of orange in color (see Figure 1)




Figure 1