



SERVICE BULLETIN

Classification: AT04-013a	Reference: NTB04-144a	Date: February 7, 2005
------------------------------	--------------------------	---------------------------

2004 – 2005 QUEST; LACK OF POWER A/T IN FAIL SAFE (3RD GEAR)

This bulletin amends NTB04-144. This version amends the Claims Information.
Please discard all paper copies of the earlier version.

- APPLIED VEHICLES:** 2004 – 2005 Quest (V42)
- APPLIED TRANSMISSION:** Equipped with 4 Speed A/T(RE4F04B) **ONLY**
- APPLIED VIN:** 2004 vehicles; all VIN's
2005 vehicles built before 5N1BV(*)8U(*)5N 101196
- APPLIED DATE:** Built before September 17, 2004

IF YOU CONFIRM:

A customer reports the following:

- The engine has low power, and/or the transmission doesn't shift (stays in 3rd gear),
and
- The incident occurs just after the engine is started,
and
- When the engine is turned OFF then restarted, the engine and transmission return to normal operation,

NOTE: This incident, if it occurs, may also have the following DTC's stored in the A/T control unit (TCM). However, the MIL will not come ON (illuminate) for these DTC's.

- VHCL SPEED SEN-A/T (Vehicle Speed Sensor Automatic Transmission [Revolution Sensor])
- VHCL SPEED SEN-MTR (Vehicle Speed Sensor-Meter)

ACTION:

Replace the A/T Control Module (TCM) with the new one listed in the parts information.

- Refer to section AT in the Service Manual (ESM) for replacement information.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART #	QUANTITY
A/T Control Module (TCM)	31036-ZF09A	1

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL A/T Control Unit (TCM)	24820-XXXXX (1) (see NOTE)	JE34AA	BD	62	(2)

- (1) Reference the FAST parts catalog and use the indicated **Speedometer Assembly** P/N as the PFP (part prefix of 24820 is provided- please use the complete applicable P/N as shown in the FAST Parts catalog).
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated FRT.

NOTE: The PFP used for this claim is different than usual. Make sure you use the PFP indicated in the Claims Information table. Do NOT use the A/T Control Module (TCM) as the PFP.

